

Inspection Photos  
Location: Wildhorse 04-0424H  
Well API: 05-123-34896, Spill ID 483043



Photo 1 – Placard



Photo 2 – Equipment Storage



Photo 3 – Stained Soil





**Inspection Photos**  
**Location: Wildhorse 04-0424H**  
**Well API: 05-123-34896, Spill ID 483043**



**Photo 4 – Stained soil at wellhead**



**Photo 5 – Fluids leaking on production equipment**



**Photo 6 – Unused Equipment**



**Inspection Photos**  
**Location: Wildhorse 04-0424H**  
**Well API: 05-123-34896, Spill ID 483043**



**Photo 4 – Stored Trucks**



**Photo 5 – Hose outside of Containment**



**Photo 6 – Hose outside of Containment**



**Inspection Photos**  
**Location: Wildhorse 04-0424H**  
**Well API: 05-123-34896, Spill ID 483043**



**Photo 5 – Original Spill location**

