

Inspection Photos
Location: Wildhorse 06-0634H
Location ID: 427410, Spill ID 480281



Photo 1 – Placard



Photo 2



Photo 3 – Inadequate wildlife protection equipment



Inspection Photos
Location: Wildhorse 06-0634H
Location ID: 427410, Spill ID 480281



Photo 4 – Active drip from closed value and plug




Photo 5 – Soil staining around wellhead



Photo 6 – Inadequate wildlife protection equipment



Inspection Photos
Location: Wildhorse 06-0634H
Location ID: 427410, Spill ID 480281



Photo 4 – Visible soil staining



Photo 5 – View facing West at original spill location



Photo 6 – original spill location remediated