

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2025

Submitted Date:

06/25/2025

Document Number:

718200044**FIELD INSPECTION FORM**Loc ID 444471 Inspector Name: Metz, Collin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10773Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 950City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT
Smith, Sydney		ssmith@fundareresources.com	
Heibel, Krystal		krystal.heibel@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444467	WELL	PR	09/01/2021	OW	123-42641	Razor 25P-2415	EI
480257	SPILL OR RELEASE	AC	10/15/2021		-	Razor 25P	EI
480867	SPILL OR RELEASE	AC	10/15/2021		-	Razor 25P	EI

General Comment:

ECMC Environmental Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 480257, Spill ID 480867 and Remediation Project #20870. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 480257

Spill Name: Razor 25P

Remediation Project #: 20870

Facility ID: 444471

Reported Date of Discovery: 07/04/2021

Date of Inspection: 06/10/2025

Weather Conditions: Sunny 85-90 F

Spill ID: 480867

Spill Name: Razor 25P

Remediation Project #: 20870

Facility ID: 444471

Reported Date of Discovery: 10/01/2021

See attached corrective actions. Form 19 - Supplementals are required.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project #20870 was created for the remediation of Spill ID 480257 pursuant to Rule 912 with Form 27 Initial Document Number 402852931 submitted on 11/01/2021. Form 27 Supplemental Document Number 403508173 submitted 08/24/2023 approved the closure requesting no further action for Remediation Project #20870. Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure that was due 10/04/2021 and 01/01/2022. Operator shall request closure of the Form 19 by checking the box for "Work proceeding under an approved Form 27 (Rule 912.c)." Operator shall submit a Form 19 Supplemental for each Spill ID requesting closure for these spills. Each spill was addressed and closed within Remediation #20870.

Corrective Action: **Operator shall submit delinquent form(s) for this project.**

Date: 07/09/2025

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718200045	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7110965