

Final Reclamation Inspection

May 15, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 310125

Inspection Document #: 718800358

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BUTTERBALL #23-19
Location ID: 310125



Photo 1. Photo taken from the well location, facing North. Photo illustrates that vegetation at the location is dominated by cheatgrass (*Bromus tectorum*), a List C noxious weed, and therefore does not meet Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: BUTTERBALL #23-19
Location ID: 310125



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: BUTTERBALL #23-19
Location ID: 310125



Photo 5. Photo taken from the access road, facing North towards the well location. Photo illustrates that vegetation has not established to Rule 1004 standards along the access road and weedy annual vegetation, including cheatgrass (*Bromus tectorum*) is present.



Photo 6. Photo taken of vegetation at the location. Photo illustrates cheatgrass (*Bromus tectorum*), has established at the well location and along the access road.

Inspection Photos
Location Name: BUTTERBALL #23-19
Location ID: 310125



Photo 7. Photo taken of the reference area, southeast of the location, facing East. Photo illustrates perennial grass vegetation with some cheatgrass encroachment.

