

Final Reclamation Inspection

May 15, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 447140

Inspection Document #: 718800363

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Butterball B4
Location ID: 447140



Photo 1. Photo taken from tank battery location, facing Southwest. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: Butterball B4
Location ID: 447140



Photo 3. Photo taken from the tank battery location, facing West, towards the access road. Photo illustrates that vegetation has not established to Rule 1004 standards at the location or along the access road.



Photo 4. Photo taken from the tank battery location and access road, facing East. See comments under Photo 3.

Inspection Photos
Location Name: Butterball B4
Location ID: 447140



Photo 5. Photo taken of the reference area, south of the location, facing Southeast. Photo illustrates perennial grass vegetation.

