

# Final Reclamation Inspection

May 23, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327359

Inspection Document #: 718800379

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BALLANTYNE USX WW #1-1  
Location ID: 327359



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that the final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: BALLANTYNE USX WW #1-1  
Location ID: 327359



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: BALLANTYNE USX WW #1-1  
Location ID: 327359



**Photo 5.** Photo taken from the tank battery location, facing East. Photo illustrates that bare ground remains at the tank battery location, and vegetation has not established to Rule 1004 standards.



**Photo 6.** Photo taken from the tank battery location, facing Northeast. See comments under Photo 5.





Inspection Photos  
Location Name: BALLANTYNE USX WW #1-1  
Location ID: 327359



**Photo 7.** Photo taken from the access road to the tank battery location, facing West towards the location. Photo illustrates that vegetation establishment does not meet Rule 1004 standards.



**Photo 8.** Photo taken from the reference area, east of the location, facing Southeast. Photo illustrates Rye (*Secale cereale*).

