

Final Reclamation Inspection

May 23, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 306028

Inspection Document #: 718800381

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ROSSMAN #42-1
Location ID: 306028



Photo 1. Photo taken from the well location, facing North. Photo illustrates that the final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: ROSSMAN #42-1
Location ID: 306028



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: ROSSMAN #42-1
Location ID: 306028



Photo 5. Photo taken from the access road, facing North away from the well location. Photo illustrates that vegetation has not established to Rule 1004 standards.



Photo 6. Photo taken from the access road, facing South towards the well location. See comments under Photo 5.



Inspection Photos
Location Name: ROSSMAN #42-1
Location ID: 306028



Photo 7. Photo taken of the reference area, North of the well site, facing West.
Photo illustrates Rye (*Secale cereale*).