

Final Reclamation Inspection

May 23, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 302883

Inspection Document #: 718800383

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WAKEFIELD #41-1
Location ID: 302883



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: WAKEFIELD #41-1
Location ID: 302883



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: WAKEFIELD #41-1
Location ID: 302883



Photo 5. Photo taken from the access road, facing North towards the well location. Photo illustrates that gravel remains along the access road (see Photo 7) and vegetation establishment does not meet Rule 1004 standards.



Photo 6. Photo taken from the access road, facing South away from the well location. See comments under Photo 5.



Inspection Photos
Location Name: WAKEFIELD #41-1
Location ID: 302883



Photo 7. Photo taken of ground cover along the access road. Photo illustrates that bare ground and gravel remains at the access road.



Photo 8. Photo taken of the reference area, south of the well location, facing Northeast. Photo illustrates weedy annual vegetation dominates the site.

