

Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 323334

Inspection Document #: 718800388

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: KAMMERZELL #1
Location ID: 323334



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards and the site is dominated by weedy annual vegetation. List B & C Noxious Weed species, including hoary cress (*Lepidium draba*), leafy spurge (*Euphorbia esula*), and cheatgrass (*Bromus tectorum*) were observed across the location.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: KAMMERZELL #1
Location ID: 323334



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: KAMMERZELL #1
Location ID: 323334



Photo 5. Photo taken from the access road, facing Southwest towards the well location. Photo illustrates that gravel remains along the access road (see Photo 7) and vegetation has not established to Rule 1004 standards. Bare ground remains and List B & C Noxious Weed species were found across the access road, including hoary cress (*Lepidium draba*), leafy spurge (*Euphorbia esula*), and cheatgrass (*Bromus tectorum*).



Photo 6. Photo taken from the access road, facing Northeast away from the well location. See comments under Photo 5.



Inspection Photos
Location Name: KAMMERZELL #1
Location ID: 323334



Photo 7. Photo taken of ground cover along the access road. Photo illustrates that bare ground and gravel remain at the access road.



Photo 8. Photo taken of ground cover at the well location. Photo illustrates that gravel and weedy annual vegetation was found at the location.



Inspection Photos
Location Name: KAMMERZELL #1
Location ID: 323334



Photo 9. Photo taken of reference area, south of the location, facing South.