

# Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 332835

Inspection Document #: 718800398

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CAMENISCH-SUPREME  
CAMP-64N66W/3SWNW  
Location ID: 332835



**Photo 1.** Photo taken from the multi-well location, from well API# 123-26201 (CAMENISCH-UPPR #6-3BX), facing North. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards and the site is dominated by weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 2.** Photo taken from the multi-well location, from well API# 123-26201 (CAMENISCH-UPPR #6-3BX), facing East. See comments under Photo 1.





Inspection Photos  
Location Name: CAMENISCH-SUPREME  
CAMP-64N66W/3SWNW  
Location ID: 332835



**Photo 3.** Photo taken from the multi-well location, from well API# 123-26201 (CAMENISCH-UPPR #6-3BX), facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the multi-well location, from well API# 123-26201 (CAMENISCH-UPPR #6-3BX), facing West. See comments under Photo 1.





Inspection Photos  
Location Name: CAMENISCH-SUPREME  
CAMP-64N66W/3SWNW  
Location ID: 332835



**Photo 5.** Photo taken from the multi-well location, from well API# 123-20231 (CAMENISCH-UPRR #6-3), facing North. See comments under Photo 1.



**Photo 6.** Photo taken from the multi-well location, from well API# 123-20231 (CAMENISCH-UPRR #6-3), facing East. See comments under Photo 1.





Inspection Photos  
Location Name: CAMENISCH-SUPREME  
CAMP-64N66W/3SWNW  
Location ID: 332835



**Photo 7.** Photo taken from the multi-well location, from well API# 123-20231 (CAMENISCH-UPRR #6-3), facing South. See comments under Photo 1.



**Photo 8.** Photo taken from the multi-well location, from well API# 123-20231 (CAMENISCH-UPRR #6-3), facing West. See comments under Photo 1.





Inspection Photos  
Location Name: CAMENISCH-SUPREME  
CAMP-64N66W/3SWNW  
Location ID: 332835



**Photo 9.** Photo taken of the access road to the multi-well location. Photo illustrates that vegetation establishment does not meet Rule 1004 standards.



**Photo 10.** Photo taken of ground cover at the multi-well location. Photo illustrates that gravel and weedy annual vegetation was found at the location. However, gravel is found across the floodplain surrounding the location, see the reference photo, Photo #11.





Inspection Photos  
Location Name: CAMENISCH-SUPREME  
CAMP-64N66W/3SWNW  
Location ID: 332835



**Photo 11.** Photo taken of reference area, east of the location, facing Northeast.  
Photo illustrates grass vegetation and gravel across the location.