

Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 447436

Inspection Document #: 718800401

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CAMENISCH CAMP 05-03B,
CAMENISCH UP RR
Location ID: 447436



Photo 1. Photo taken of the northern portion of the tank battery location, facing Northeast. Photo illustrates that final reclamation activities appear to have taken place, but gravel remains and vegetation has not established to Rule 1004 standards. Weedy annual vegetation including cheatgrass (*Bromus tectorum*) was observed across the location.



Photo 2. Photo taken from the northern portion of the tank battery location, facing South. See comments under Photo 1.



Inspection Photos

Location Name: CAMENISCH CAMP 05-03B,

CAMENISCH UP RR

Location ID: 447436



Photo 3. Photo taken from the southern portion of the tank battery location, facing North. See comments under Photo 1.



Photo 4. Photo taken from the southern portion of the tank battery location, facing South. See comments under Photo 1.



Inspection Photos

Location Name: CAMENISCH CAMP 05-03B,

CAMENISCH UP RR

Location ID: 447436



Photo 5. Photo taken of ground cover at the tank battery location. Photo illustrates that gravel remains and cheatgrass (*Bromus tectorum*), a List C Noxious Weed, was observed across the location.



Photo 6. Photo taken of the reference area, north of the tank battery location, facing East. Photo illustrates that weedy annual vegetation is present at the reference location.

