

Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 332848

Inspection Document #: 718800404

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name:
CAMENISCH-UPRR-64N66W/3NENW
Location ID: 332848



Photo 1. Photo taken from the multi-well location, from well API# 123-10950 (CAMENISCH-UPRR #1-3), facing North. Photo illustrates that final reclamation activities have taken place, but gravel remains, vegetation has not established to Rule 1004 standards and the site is dominated by weedy annual vegetation. List B and C Noxious Weed Species were observed across the location, including leafy spurge (*Euphorbia esula*) and cheatgrass (*Bromus tectorum*).



Photo 2. Photo taken from the multi-well location, from well API# 123-10950 (CAMENISCH-UPRR #1-3), facing East. See comments under Photo 1.



Inspection Photos
Location Name:
CAMENISCH-UPRR-64N66W/3NENW
Location ID: 332848



Photo 3. Photo taken from the multi-well location, from well API# 123-10950 (CAMENISCH-UPRR #1-3), facing South. See comments under Photo 1.



Photo 4. Photo taken from the multi-well location, from well API# 123-10950 (CAMENISCH-UPRR #1-3), facing West. See comments under Photo 1.

Inspection Photos
Location Name:
CAMENISCH-UPRR-64N66W/3NENW
Location ID: 332848



Photo 5. Photo taken from the multi-well location, from well API# 123-26460 (CAMENISCH-UPRR #1-3B), facing North. See comments under Photo 1.



Photo 6. Photo taken from the multi-well location, from well API# 123-26460 (CAMENISCH-UPRR #1-3B), facing East. See comments under Photo 1.

Inspection Photos
Location Name:
CAMENISCH-UPRR-64N66W/3NENW
Location ID: 332848



Photo 7. Photo taken from the multi-well location, from well API# 123-26460 (CAMENISCH-UPRR #1-3B), facing South. See comments under Photo 1.



Photo 8. Photo taken from the multi-well location, from well API# 123-26460 (CAMENISCH-UPRR #1-3B), facing West. See comments under Photo 1.



Inspection Photos

Location Name:

CAMENISCH-UPRR-64N66W/3NENW

Location ID: 332848



Photo 9. Photo taken of the access road to the multi-well location. Photo illustrates that vegetation establishment does not meet Rule 1004 standards and gravel remains across the access road.



Photo 10. Photo taken of ground cover at the multi-well location. Photo illustrates that gravel and weedy annual vegetation was found at the location, including List B & C Noxious Weeds species leafy spurge (*Euphorbia esula*) and cheatgrass (*Bromus tectorum*).



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718800404

Inspection Photos
Location Name:
CAMENISCH-UPRR-64N66W/3NENW
Location ID: 332848



Photo 11. Photo taken of reference area, north of the location, facing Southeast.
Photo illustrates perennial grass vegetation.

