

Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 447324

Inspection Document #: 718800407

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CAMENISCH UPRR 01-03, 01-03B

Location ID: 447324



Photo 1. Photo taken of the southern portion of the tank battery location, facing North. Photo illustrates that final reclamation activities appear to have taken place, but gravel remains and vegetation has not established to Rule 1004 standards. Weedy annual vegetation including cheatgrass (*Bromus tectorum*) was observed across the location.



Photo 2. Photo taken from the southern portion of the tank battery location, facing South. See comments under Photo 1.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718800407

Inspection Photos

Location Name: CAMENISCH UPRR 01-03, 01-03B

Location ID: 447324



Photo 3. Photo taken of the northern portion of the tank battery location, from the access road, facing East. See comments under Photo 1.



Photo 4. Photo taken from the northern portion of the tank battery location, facing South. Photo illustrates that midstream equipment remains on the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718800407

Inspection Photos

Location Name: CAMENISCH UPRR 01-03, 01-03B

Location ID: 447324



Photo 5. Photo taken of midstream equipment at the tank battery location.



Photo 6. Photo taken of the reference area, east of the tank battery location, facing East. Photo illustrates that weedy annual vegetation is present at the reference location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 718800407