

Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329883

Inspection Document #: 718800411

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RUMSEY #3-1216
Location ID: 329883



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, however the location does not meet Rule 1004 standards as the site is dominated by weedy annual vegetation including kochia (*Kochia scoparia*).



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: RUMSEY #3-1216
Location ID: 329883



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: RUMSEY #3-1216
Location ID: 329883



Photo 5. Photo taken of the access road, facing North away from the well location. Photo illustrates that weedy annual vegetation is present throughout the well location and access road.



Photo 6. Photo taken of the access road, facing South towards the well location. See comments under Photo 5.



Inspection Photos
Location Name: RUMSEY #3-12I6
Location ID: 329883



Photo 7. Photo taken of ground cover at the well site. Photo illustrates weedy annual vegetation including kochia (*Kochia scoparia*).



Photo 8. Photo taken of the reference area, northwest of the location, facing West. Photo illustrates perennial grass vegetation.

