

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404259371

Date Received:

06/27/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10634

Name of Operator: P O & G OPERATING LLC

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Charlotte Nash

713-589-8186

charlotte\_nash@pogresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 717100245

Inspection Date: 05/30/2025

FIR Submit Date: 06/16/2025

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: P O & G OPERATING LLC

Company Number: 10634

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

#### LOCATION - Location ID: 433807

Location Name: NININGER Number: 11-1-1645 County: \_\_\_\_\_

Qtrqtr: Lot 4 Sec: 1 Twp: 16S Range: 45W Meridian: 6

Latitude: 38.694210 Longitude: -102.418580

#### FACILITY - API Number: 05-017-00 Facility ID: 488940

Facility Name: Nininger Wellhead Number: \_\_\_\_\_

Qtrqtr: Lot 4 Sec: 1 Twp: 16S Range: 45W Meridian: 6

Latitude: 38.694210 Longitude: -102.418580

### CORRECTIVE ACTIONS:

1 CA# 205637

Corrective Action: Secure access to excavation in accordance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.

Date: 06/30/2025

Response: CA COMPLETED

Date of Completion: 06/26/2025

Operator  
Comment:

Excavation was to pull background sample in a non-contaminated area. Excavation has been backfilled.

ECMC Decision: \_\_\_\_\_

Corrective Action:	Operator shall comply with Rule 913.b.(5).B.iv. and properly store, handle, and manage all E&P Waste to prevent contamination of stormwater, surface water, Groundwater, and soil.
--------------------	--

Date: \_\_\_\_\_

Date of Completion: 06/26/2025

Operator Comment:	The excavation was to take a background sample in a non-contaminated area. Excavation has been backfilled.
-------------------	--

ECMC Decision:

\_\_\_\_\_

Print Name: Charlotte Nash Signed:

Title: Supervisor Regulatory Date: 6/27/2025 11:19:44 AM

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404259406	RESPONSE PHOTOS

Total Attach: 1 Files