

QUASAR ENERGY SERVICES, INC.

10/1/2024




www.quasarenergyservices.com

3288 FM 51
Gainesville, Texas 76240
Office: 940-612-3336

Fax: 940-612-3336 | qesi@qeserve.com

FRACTURING | ACID | CEMENT | NITROGEN



| | |
|------------------------------------------------------|--------------------------------------------|
| BID #: 9945 | AFE#/PO#: 0 |
| TYPE / PURPOSE OF JOB: LONGSTRING | SERVICE POINT: Liberal, KS |
| CUSTOMER: BLUE STAR HELIUM | WELL NAME: JACKSON #2L |
| ADDRESS: | LOCATION: KIM COLORADO |
| CITY: LAS ANIMAS STATE: CO ZIP: | COUNTY: LAS ANIMAS STATE: CO |

| DATE OF SALE: 5/1/2025 | | | | Perforations: to | | | |
|-------------------------------|------|----|----------|----------------------------------------|------------|-------------|--|
| QTY. | CODE | YD | UNIT | PUMPING AND EQUIPMENT USED | UNIT PRICE | AMOUNT | |
| 200 | 1000 | L | Mile | Mileage - Pickup - Per Mile | \$5.69 | \$ 1,138.00 | |
| 400 | 1010 | L | Mile | Mileage - Equipment Mileage - Per Mile | \$8.89 | \$ 3,556.00 | |
| 1 | 5622 | L | Per Well | Pumping Service Charge -1 | \$2,361.56 | \$ 2,361.56 | |
| 1 | 4690 | L | Each | Top Rubber Plug 7" | \$103.72 | \$ 103.72 | |

Subtotal for Pumping & Equipment Charges \$ 7,159.28

| QTY. | CODE | YD | UNIT | MATERIALS | UNIT PRICE | AMOUNT | |
|-------|------|----|----------|--------------------------------|------------|-------------|--|
| 290 | 5635 | L | Per Sack | Cement - Class A (LB) | \$24.01 | \$ 6,962.90 | |
| 4 | 5751 | L | Per Gal | C-41L Defoamer Liquid | \$49.60 | \$ 198.40 | |
| 40 | 5801 | L | per Lb. | Fiber Lock | \$7.87 | \$ 314.80 | |
| 800 | 5803 | L | Per Lbs. | Tactical Blitz | \$2.68 | \$ 2,144.00 | |
| 3,350 | 5890 | L | Per Lb. | Salt | \$0.54 | \$ 1,809.00 | |
| 400 | 5900 | L | Per Lb. | Sodium Metasilicate (SMS) C-45 | \$2.49 | \$ 996.00 | |
| 100 | 5930 | L | Per Lb. | Sugar | \$2.84 | \$ 284.00 | |
| 840 | 5952 | L | Per Gal | MS Spacer | \$2.19 | \$ 1,839.60 | |

MANHOURS: 12 # WORKERS: 3

Subtotal for Material Charges \$ 14,548.70

WORKERS

TOTAL \$ 21,707.98

JESSE PAXTON

DISCOUNT: 20%

DISCOUNT \$ 4,341.60

DANNY MCLANE

DISCOUNTED TOTAL \$ 17,366.38

JOSE MARTINEZ

STAMPS & NOTES:

As of 9/22/15 any invoice with a discount must paid within 60 days of the invoice date. After 60 days the discount will be removed and the invoice will reflect full price.

CUSTOMER SIGNATURE & DATE

Signature: *[Signature]* Date: 5/1/25

*All accounts are past due net 30 days following the date of invoice. A finance charge of 1-1/2% per month or 18% annual percentage rate will be charged on all past due accounts.

Print Name: *Trent A. Smith*

QUASAR ENERGY SERVICES, INC.

3288 FM 51

Gainesville, Texas 76240

Office: 940-612-3336

Fax: 940-612-3336 | qesi@qeserve.com

Form 185-2r

5/1/25

CEMENTING JOB LOG

CEMENTING JOB LOG

[illegible]



Job Safety Analysis Checklist -JSA

Form 181-4/185-2

10/1/24
JSA

Company: BLUE STAR HELIUM

Date: 5/1/25

Location: KIM COLORADO

Well Name: JACKSON #2L

Weather: CLOUDY

Temp.: 60

Wind Direction: N

Type of Job: LONGSTRING

Person in Charge: JESSE PAXTON

Line Boss: DANNY MCLANE

Emergency Driver: JOSE MARTINEZ

| Emergency Info. | PPE/Body Hazards | Confined Space |
|---------------------------------------------------------------|-------------------------------------------------------------------|------------------------------------------------------------|
| <input type="checkbox"/> Eye Wash | <input checked="" type="checkbox"/> Hard hat | <input type="checkbox"/> Rescue Plan |
| <input type="checkbox"/> Shower Station | <input checked="" type="checkbox"/> Hearing Protection | <input type="checkbox"/> Hole Watch / Communication |
| <input type="checkbox"/> Fire Extinguishers Loc/Tag | <input checked="" type="checkbox"/> Proper Work Boots | <input type="checkbox"/> Atmosphere Testing |
| <input checked="" type="checkbox"/> Evacuation Route / Muster | <input checked="" type="checkbox"/> Eye Protection | <input type="checkbox"/> Ventilation |
| <input checked="" type="checkbox"/> Leak/Spill Reporting | <input checked="" type="checkbox"/> Hand Protection | <input type="checkbox"/> Respirator |
| <input checked="" type="checkbox"/> Fire Reporting | <input checked="" type="checkbox"/> Flame Resistant Clothing FR | Tools / H2O |
| | <input checked="" type="checkbox"/> Fall protection | <input checked="" type="checkbox"/> Right Tool for the Job |
| | <input checked="" type="checkbox"/> Lock Out / Tag Out | <input checked="" type="checkbox"/> Inspection |
| | <input checked="" type="checkbox"/> Respiratory- Silica, Chemical | <input checked="" type="checkbox"/> Drinking Water |

Hospital Information

Hospital:

Phone #:

Address:

| Scope of Work | Potential Hazards | Safety Controls |
|---------------------|---------------------------------|-------------------------|
| 1 RIG UP | HEAVY LIFTING; LIFTING OVERHEAD | TEAMWORK, COMMUNICATION |
| 2 PUMPING OPERATION | PRESSURIZED LINES | TEAMWORK, COMMUNICATION |
| 3 RIG DOWN | HEAVY LIFTING; LIFTING OVERHEAD | TEAMWORK, COMMUNICATION |

| Print Name | Signature | Company |
|-----------------|-----------|---------|
| 1 JESSE PAXTON | | Des |
| 2 DANNY MCLANE | | Des |
| 3 JOSE MARTINEZ | | Des |
| 4 | | |
| 5 | | |
| 6 | | |
| 7 | | |
| 8 | | |
| 9 | | |
| 10 | | |
| 11 | | |
| 12 | | |
| 13 | | |
| 14 | | |
| 15 | | |
| 16 | | |
| 17 | | |
| 18 | | |
| 19 | | |
| 20 | | |
| 21 | | |
| 22 | | |
| 23 | | |

Total # Workers:

BLUE STAR HELIUM JACKSON #2L LONGSTRING 5-1-25

