

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8844 Entrance to location



Photo # 8901 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8847 Location



Photo # 8879 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8889 Location



Photo # 8897 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8908 Location



Photo # 8910 Location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8914 SW corner of location



Photo # 8915 NW corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8916 NE corner of location



Photo # 8917 SE corner of location

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8848 Wellhead sign is not legible/not in compliance with CECMC rules

Photo # 8850 Wellhead sign is not legible/not in compliance with CECMC rules

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8858 Wellhead sign is not legible/not in compliance with CECMC rules



Photo # 8861 Wellhead sign is not legible/not in compliance with CECMC rules

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8866 Unused flowline does not comply with CECMC 600 & 1100 series rules



Photo # 8893 Unused flowline does not comply with CECMC 600 & 1100 series rules

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8894 Unused flowline does not comply with CECMC 600 & 1100 series rules

Photo # 8871 Chemical tank lacks required labeling/not in compliance with CECMC rules

Inspection/Audit Photos

Location: LARAMIE ENERGY LLC Homer Deep Unit 7-23 PAD

Location ID: 436835

Date: 06/26/2025



Photo # 8911 Unused equipment on location



Photo # 8912 Unused equipment on location