

# Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328857

Inspection Document #: 718800415

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: RUMSEY #10-4  
Location ID: 328857



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that the location does not meet Rule 1004 standards as gravel remains on location and the vegetation is dominated by cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: RUMSEY #10-4  
Location ID: 328857



**Photo 3.** Photo taken from the well location, facing South. Equipment remains at the well site.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: RUMSEY #10-4  
Location ID: 328857



**Photo 5.** Photo taken of the equipment remaining on the well site.



**Photo 6.** Photo taken of ground cover at the well site. Photo illustrates gravel and cheatgrass (*Bromus tectorum*), a List C Noxious weed species.



Inspection Photos  
Location Name: RUMSEY #10-4  
Location ID: 328857



**Photo 7.** Photo taken of the access road, facing South towards the well location. Photo illustrates that vegetation establishment along the access road does not meet Rule 1004 standards and gravel remains across the location.



**Photo 8.** Photo taken of the access road, facing Northwest away from the well location. See comments under Photo 7.



Inspection Photos  
Location Name: RUMSEY #10-4  
Location ID: 328857



**Photo 9.** Photo taken of the reference area, southeast of the well location, facing Southeast.