

# Inspection Photos

ID: 460776

Operator: AXIS EXPLORATION LLC

Inspection Date: 6/25/2025

County: ELBERT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the former tank battery facility. This location is not reclaimed. Soils appear to be compacted and there are undesirable weeds.





## Inspection Photos



**Photo 2.** There are bare compacted soils and undesirable weeds that need to be controlled.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 3.** Facing north at the former tank battery facility.

