

# Inspection Photos

API: 039-06630

Operator: AXIS EXPLORATION LLC

Inspection Date: 6/25/2025

County: ELBERT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the former wellsite. The location is not reclaimed and there are tall noxious weeds that must be controlled.



## Inspection Photos



**Photo 2.** Facing southeast toward the former wellsite. The location is not reclaimed and there are tall noxious weeds that must be controlled.

