

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2025

Submitted Date:

06/30/2025

Document Number:

718200051

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Metz, Collin 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone | Email   | Comment |
|------------------|-------|---|---------|
| Anderson, Laurel |       | laurel.anderson@state.co.us                           |         |
| Graber, Nikki    |       | nikki.graber@state.co.us                              |         |
| ,                |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com |         |

**Inspected Facilities:**

| Facility ID | Type                | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|---------------------|--------|-------------|------------|-----------|--------------------|-------------|
| 248518      | WELL                | PA     |             | OW         | 123-16316 | LDS WHITE D 19-15  | EI          |
| 489269      | SPILL OR<br>RELEASE | AC     | 02/11/2025  |            | -         | LDS White D #19-15 | EI          |

**General Comment:****ECMC Environmental Field Inspection Report Summary**

This is an environmental inspection to determine progress on Spill ID 489269 and Remediation Project #30826. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 489269

Spill Name: LDS White D #19-15

Remediation Project #: 30826

Well API: 05-123-16316

Reported Date of Discovery: 02/07/2025

Date of Inspection: 06/12/2025

Weather Conditions: Sunny/Breezy 85-90 F

Spills are located within or adjacent to:

-Multiple jurisdictional wetlands

Current Site Status:

-Backfilled and interim reclamation started

See attached corrective actions. A Form 19 - Supplemental is required.

| Inspected Facilities   |        |       |          |             |           |         |    |               |    |
|--|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID:   | 248518 | Type: | WELL     | API Number: | 123-16316 | Status: | PA | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |
| Facility ID:   | 489269 | Type: | SPILL OR | API Number: | -         | Status: | AC | Insp. Status: | EI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 |        |       |          |             |           |         |    |               |    |

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: A historical release was discovered on 02/07/2025 during Remediation Project 30826 and the Form 19 Initial with Supplemental Report (Doc # 404087102) was received on 02/10/2025. Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure that was due 05/08/2025 and is 49 days late. Operator shall submit and request closure of the Form 19 by checking the box for "Work proceeding under an approved Form 27 (Rule 912.c)" for this project within 14 days. Operator is out of compliance with Rule 913.e.(3).

Corrective Action: **Operator shall submit delinquent form for this project.**

Date: 07/14/2025

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 718200052    | Photo Log   | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7121914">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7121914</a> |