

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2025

Submitted Date:

06/30/2025

Document Number:

718200053**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Metz, Collin 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kiel, Macy		Macy_Kiel@oxy.com	All Inspections
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Graber, Nikki		nikki.graber@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	
,		ECMCInspections@oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420912	WELL	PA		OW	123-32747	UPRC H17-99HZ	EI
489842	SPILL OR RELEASE	AC	04/24/2025		-	UPRC H17-99HZ Wellhead	EI

General Comment:

ECMC Environmental Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 489842 and Remediation Project #27009. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 489842

Spill Name: UPRC H17-99HZ Wellhead

Remediation Project #: 27009

Well API: 05-123-32747

Reported Date of Discovery: 04/10/2025

Date of Inspection: 06/12/2025

Weather Conditions: Sunny 85-90 F

Spills are located within or adjacent to:

-Livestock grazing area

Current Site Status:

-Reclamation activities in process

-Unused equipment

-Unlabeled stockpiles with inadequate earthen berms within reclamation area

See attached corrective actions. A Form 19 - Supplemental is required.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (see attached photo)		
Corrective Action:	Comply with Rule 606		Date: 07/15/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420912	Type:	WELL	API Number:	123-32747	Status:	PA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	489842	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Operator request for closure was approved for Remediation Project #27009 through Supplemental Form 27 (Doc #403800301) submitted 09/19/2024. During reclamation activities historically impacted soil was discovered and Spill ID 489842 was created through Initial Form 19 (Doc #404161166) submitted 04/11/2025. The last Supplemental Form 19 Report (Doc # 404168968) was received on 04/18/2025. Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure that is due 07/09/2025.

Corrective Action: **Submit Supplemental Form 19 to meet requirements of Rule 912.b.(6)**

Date: 07/09/2025

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type Management Condition GPS (Lat) (Long)

Comment: Soil is stockpiled on location with no BMP's present.

Corrective Action: **Manage waste in compliance with Rule 913.b.(3) and ECMC Guidance 913.b.(5)B.i-v.**

Date: 07/30/2025

Spill/Remediation:

Comment: _____

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718200054	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7121915