

Final Reclamation Inspection

May 28, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328786

Inspection Document #: 718800394

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CAMENISCH - SUPREME CAMP #4-3
Location ID: 328786




Photo 1. Google Earth aerial imagery from October 14, 2017. Photo illustrates the well location, access road, and associated off-location tank battery during active operations.



Inspection Photos
Location Name: CAMENISCH - SUPREME CAMP #4-3
Location ID: 328786



Photo 2. Google Earth Aerial Imagery from March 2, 2025. Photo illustrates the well location, access road, and associated off-location tank battery after plugging operations. The well location is contained within a land use change.

Inspection Photos

Location Name: CAMENISCH - SUPREME CAMP #4-3

Location ID: 328786



Photo 3. Photo taken from the well location, facing North. Photo illustrates that the location is contained within a land use change.



Photo 4. Photo taken from the well location, facing East. See comments under Photo 3.



Inspection Photos

Location Name: CAMENISCH - SUPREME CAMP #4-3

Location ID: 328786



Photo 5. Photo taken from the well location, facing South. See comments under Photo 3.



Photo 6. Photo taken from the well location, facing West. See comments under Photo 3.



Inspection Photos

Location Name: CAMENISCH - SUPREME CAMP #4-3

Location ID: 328786



Photo 7. Photo taken of the well location. Photo illustrates that the flowlines which were previously abandoned in place have been exposed at the well site.



Photo 8. Photo taken of the well site. Photo illustrates flowlines exposed by the land use change at the well site.



Inspection Photos

Location Name: CAMENISCH - SUPREME CAMP #4-3

Location ID: 328786



Photo 9. Photo taken of the tank battery location, facing West. Photo illustrates that final reclamation activities have taken place, however vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location.



Photo 10. Photo taken of the tank battery location, facing East. See comments under Photo 9.



Inspection Photos

Location Name: CAMENISCH - SUPREME CAMP #4-3

Location ID: 328786



Photo 11. Photo taken of reference area, east of the tank battery location, facing Northeast.

