

Final Reclamation Inspection

June 5, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 327901

Inspection Document #: 718800422

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MOSER #34-3G
Location ID: 327901



Photo 1. Photo taken from the well location, facing North. Photo illustrates that the well location meets Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: MOSER #34-3G
Location ID: 327901



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: MOSER #34-3G
Location ID: 327901



Photo 5. Photo taken the tank battery location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 6. Photo taken of the tank battery location, facing Northwest. See comments under Photo 5.

Inspection Photos
Location Name: MOSER #34-3G
Location ID: 327901



Photo 7. Photo taken of the tank battery location, facing Northeast. See comments under Photo 5.



Photo 8. Photo taken of the reference area for the tank battery location, northwest of the location, facing Southwest.



Inspection Photos
Location Name: MOSER #34-3G
Location ID: 327901



Photo 9. Photo taken of the reference area, southeast of the well location, facing South. Photo illustrates alfalfa cropland.