

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Jun 26, 2025 at 1:13:54 PM
+39.372806,-108.367441 ±3.76m



Jun 26, 2025 at 1:32:15 PM
+39.372649,-108.367480 ±3.67m

Photo # 8932 Entrance to location

Photo # 8959 Location

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Photo # 8933 Location



Photo # 8948 Location

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Photo # 8958 Location



Photo # 8986 SE corner of location

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Photo # 8987 SW corner of location



Photo # 8988 NW corner of location

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Photo # 8989 NE corner of location



Photo # 8939 Staining

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Photo # 8945 Staining



Photo # 8954 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Photo # 8965 Open ended piping on production tank/wildlife hazard/available for entry by wildlife



Photo # 8974 Open ended piping on production tank/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025




Photo # 8992 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 8993 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Photo # 8994 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 8995 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard

Inspection/Audit Photos

Location: VISION ENERGY LLC SOUTH SHALE RIDGE 10-7 PAD

Location ID: 323851

Date: 06/26/2025



Photo # 8999 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard



Photo # 9001 Weeds/undesirable plant species surrounding production equipment constitutes a fire hazard