

# Final Reclamation and Stormwater Inspection

June 27, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336171

Well Name: UPRR 50 PAN UT "F" TRUE-62N66W/27SWNW

Inspection Document #: 718600724

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: UPRR 50 PAN UT "F"  
TRUE-62N66W/27SWNW  
Location ID: 336171



**Photo 1.** Picture taken from the south side of the tank battery looking north. Gravel remains on the tank battery and the location is unreclaimed.



**Photo 2.** Looking east down the south side of the tank battery location. List B noxious weed scotch thistle is present on location.





Inspection Photos  
Location Name: UPRR 50 PAN UT "F"  
TRUE-62N66W/27SWNW  
Location ID: 336171



**Photo 3.** Looking northeast across the two wellbores on location. Bare soil is present. Vegetation around the wellbore area is primarily undesirable weed kochia and list C noxious weed cheatgrass.



**Photo 4.** Looking south across the eastern well area. See photo 3 comments.





Inspection Photos  
Location Name: UPRR 50 PAN UT "F"  
TRUE-62N66W/27SWNW  
Location ID: 336171



**Photo 5.** Looking south from the wellbore area. See photo 3 comments.



**Photo 6.** Looking east from the wellbore area. See photo 3 comments.





Inspection Photos  
Location Name: UPRR 50 PAN UT "F"  
TRUE-62N66W/27SWNW  
Location ID: 336171



**Photo 7.** Looking north from the wellbore area. See photo 3 comments.



**Photo 8.** Looking west from the wellbore area. See photo 3 comments.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 718600724



Inspection Photos  
Location Name: UPRR 50 PAN UT "F"  
TRUE-62N66W/27SWNW  
Location ID: 336171



**Photo 9.** Reference area to the south of the well location.

