

Final Reclamation and Stormwater Inspection

June 27, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 318688

Well Name: OLIVE #1

Inspection Document #: 718600727

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: OLIVE #1
Location ID: 318688



Photo 1. Picture taken from the north side of the tank battery. looking north across the wellhead. The wellhead is located in a road that appears to be unused. The road dead ends at a fence.



Photo 2. looking south across the wellhead area. A slight depression is present around the well area. Bare soil and gravel is present at the wellhead.



Inspection Photos
Location Name: OLIVE #1
Location ID: 318688



Photo 3. picture taken at the end of the unused road at on the north side of the location. Road is fenced off.



Photo 4. Looking west across the north side of the location.

