

## Inspection Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Photo # 9040 From Entrance to location



Photo # 9041 Location

## Inspection Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Photo # 9042 Location



Photo # 9043 Location



## Inspection Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Photo # 9044 Location



Photo # 9045 Location



## Inspection Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942




Photo # 9046 Location



Photo # 9047 Possible tank failure



## Inspection Photos

Location Name: QB ENERGY OPERATING LLC CRAIG (K35NW) 35-12C Pad

Location #: 334942



Photo # 9048 Possible tank failure



Photo # 9049 Possible tank failure