

697-03-07
07-01-25

697-03-07
07-01-2025



697-03-07
07-01-25






697-03-07
07-01-2025

697-03-07
07-01-25




697-03-07
07-01-2025

A photograph showing a dirt path or trench cutting through a field of green, low-lying vegetation. A wooden post is visible on the left side of the path. The image has yellow text overlaid in the top left corner.

A photograph of a dry, rocky hillside. A drainage ditch, lined with stacked stones, runs diagonally down the slope. A corrugated metal pipe is visible in the foreground, partially buried in the ground. The background shows a line of trees under a blue sky with some clouds.


697-03-07
07-01-2025

A photograph showing a dirt path leading through a wooded area. The path is in the center, leading towards a fence and a hill in the background. The fence is made of wire and has a wooden post. The hill is covered in green grass. The text "697-03-07" and "07-01-2025" is overlaid in yellow on the path.

697-03-07
07-01-2025

A photograph of a steep, eroded hillside. A fence line with wooden posts and wire runs diagonally across the upper left portion of the image. The hillside is covered in green shrubs and grass, with exposed brown soil and roots visible in the eroded areas. In the foreground, a large, dark, cylindrical object, possibly a pipe or a large rock, lies on the ground. The sky is clear and blue.


697-03-07
07-01-25

A photograph of a field with a black corrugated pipe and a log. The pipe is lying on the ground, and the log is lying on the ground. The background is a field with green vegetation. The text "697-03-07" and "07-01-2025" is overlaid on the image.


697-03-07
07-01-2025



697-03-07
07-01-2025

A photograph of a construction site. In the background, there is a large pile of light-colored rocks and a long, thick log lying horizontally. The ground is dirt. In the foreground, a black corrugated pipe is visible, extending from the bottom right towards the center. A black metal post is also visible on the right side. The scene is surrounded by green vegetation.

697-03-07
07-01-2025



697-03-07
07-01-25

697-03-07
07-01-2025



697-03-07
07-01-25






697-03-07
07-01-2025

697-03-07
07-01-25




697-03-07
07-01-2025






697-03-07
07-01-2025

A photograph showing a dirt path or trail leading through a wooded area. The path is in the center, leading towards a fence line and a grassy hill in the background. There are trees and bushes on the left side of the path. The ground is covered with dirt and some rocks. Overlaid on the image is yellow text.

697-03-07
07-01-2025

A photograph of a steep, eroded hillside. A fence line with wooden posts and wire runs diagonally across the upper left portion of the image. The hillside is covered in green shrubs and grass, with exposed brown soil and roots visible in the eroded areas. In the foreground, a large, dark, cylindrical object, possibly a pipe or a large rock, lies horizontally across the lower center. The sky is clear and blue.


697-03-07
07-01-25

A photograph of a field with a black corrugated pipe and a log. The pipe is lying on the ground, and the log is lying on the ground. The background is a field with green vegetation and a wire fence.

697-03-07
07-01-2025



697-03-07
07-01-2025

A photograph of a construction site. In the background, there is a large pile of light-colored rocks and a large log lying horizontally. The ground is dirt. In the foreground, a black corrugated pipe is visible, extending from the bottom right towards the center. A black metal post is also visible on the right side. The text "697-03-07" and "07-01-2025" is overlaid in the center of the image.

697-03-07
07-01-2025