

Inspection Photos

June 26th, 2025

Operator: Simcoe LLC

Location ID: 325351

Inspection Document #: 714002244

La Plata County, CO

Township: SENW 16 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

June 26, 2025
319° NW



Photo 1. View of well pad taken from the southern edge facing



June 26, 2025
60° NE



Photo 3. Large patch of Musk Thistle observed on active pad.

June 26, 2025
355° N



Photo 4. Additional view of weeds (Cheatgrass) and vegetation encroaching on equipment.