

Inspection Photos

June 26th, 2025

Operator: BP America Production

Location ID: 325081

Inspection Document #: 714002247

La Plata County, CO

Township: NWSE 31 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Wilde 1
Location ID: 325081

June 26, 2025
26° NE



Photo 1. View of the project area taken from the southern edge facing center.

Inspection Photos
Location Name: Wilde 1
Location ID: 325081



Photo 2. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Wilde 1
Location ID: 325081



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: reclaimed well pad appears consistent with adjacent reference areas.

June 26, 2025
359° N





Inspection Photos
Location Name: Wilde 1
Location ID: 325081



June 26, 2025
310° NW

Photo 6. Reference area composed predominantly of Baltic Rush and Timothee.