

# Final Reclamation Inspection

June 5, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329613

Inspection Document #: 718800431

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-ARISTOCRAT #12-34A  
Location ID: 329613



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that vegetation has not established to Rule 1004 standards on the location as there is bare ground and weedy annual vegetation, including cheatgrass (*Bromus tectorum*).



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: HSR-ARISTOCRAT #12-34A  
Location ID: 329613



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-ARISTOCRAT #12-34A  
Location ID: 329613



**Photo 5.** Photo taken of the access road to the well location, facing east. Photo illustrates that bare ground, gravel, and weedy annual vegetation remains along the road.



**Photo 6.** Photo taken of the access road to the well location, facing west. Photo illustrates that final reclamation activities have not taken place and the site is dominated by weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.





Inspection Photos  
Location Name: HSR-ARISTOCRAT #12-34A  
Location ID: 329613



**Photo 7.** Photo taken of the access road to the well location, facing southeast. Photo illustrates that a partially-collapsed culvert remains on the access road.



**Photo 8.** Photo taken of the access road. Photo illustrates gravel and a culvert remaining at the location.



Inspection Photos  
Location Name: HSR-ARISTOCRAT #12-34A  
Location ID: 329613



**Photo 9.** Photo taken of the tank battery location, facing West. Photo illustrates the location does not meet Rule 1004 standards as it is dominated by weedy, annual vegetation.



**Photo 10.** Photo taken of the tank battery location, facing North. See comments under Photo 9.



Inspection Photos  
Location Name: HSR-ARISTOCRAT #12-34A  
Location ID: 329613



**Photo 11.** Photo taken of the tank battery location, facing East. See comments under Photo 9.



**Photo 12.** Photo taken ground cover at the tank battery location. Photo illustrates weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, and kochia (*Bassia scoparia*).





Inspection Photos  
Location Name: HSR-ARISTOCRAT #12-34A  
Location ID: 329613



**Photo 13.** Photo taken of the reference area to the tank battery, south of the location, facing South. Photo illustrates perennial grass vegetation with some cheatgrass (*Bromus tectorum*) encroachment, and sand sagebrush (*Artemisia filifolia*).



**Photo 14.** Photo taken of the reference area for the well location, south of the location, facing south. Photo illustrates perennial grass vegetation.