

# Final Reclamation Inspection

June 5, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 329614

Inspection Document #: 718800433

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-HOUSTON #13-34A  
Location ID: 329614



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that the well site meets Rule 1004 standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-HOUSTON #13-34A  
Location ID: 329614



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-HOUSTON #13-34A  
Location ID: 329614



**Photo 5.** Photo taken of the access road to the well location, facing east. Photo illustrates that the access road has not been reclaimed and bare ground and gravel remain.



**Photo 6.** Photo taken of ground cover at the access road. Photo illustrates gravel remains across the road.





Inspection Photos  
Location Name: HSR-HOUSTON #13-34A  
Location ID: 329614



**Photo 7.** Photo taken of the access road to the well location, facing north, away from the location. See comments under Photo 5.



**Photo 8.** Photo taken of the tank battery location, facing South. Photo illustrates that vegetation has not established to Rule 1004 standards at the location.





Inspection Photos  
Location Name: HSR-HOUSTON #13-34A  
Location ID: 329614



**Photo 9.** Photo taken of the tank battery location, facing West. See comments under Photo 8.



**Photo 10.** Photo taken of the tank battery location, facing North. See comments under Photo 8.



Inspection Photos  
Location Name: HSR-HOUSTON #13-34A  
Location ID: 329614



**Photo 11.** Photo taken of the reference area to the well location, located north of the location, facing North. Photo illustrates perennial grass vegetation.



**Photo 12.** Photo taken of the reference area to the tank battery location, located west of the location, facing west. Photo illustrates perennial grass vegetation.

