

# Final Reclamation Inspection

June 12, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 330386

Inspection Document #: 718800441

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-FOSTER #4-35  
Location ID: 330386



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that vegetation establishment at the well site meets Rule 1004 standards.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-FOSTER #4-35  
Location ID: 330386



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.





Inspection Photos  
Location Name: HSR-FOSTER #4-35  
Location ID: 330386



**Photo 5.** Photo taken of the access road to the well location, facing South. Photo illustrates that final reclamation activities have taken place, but weedy annual vegetation is present at the entrance to the access road.



**Photo 6.** Photo taken of the access road, from the well location, facing South away from the location. Photo illustrates that vegetation has established to Rule 1004 standards across this portion of the access road.



Inspection Photos  
Location Name: HSR-FOSTER #4-35  
Location ID: 330386



**Photo 7.** Photo taken of the tank battery location, facing East. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location.



**Photo 8.** Photo taken of the tank battery location, facing West. See comments under Photo 7.





Inspection Photos  
Location Name: HSR-FOSTER #4-35  
Location ID: 330386



**Photo 9.** Photo taken of the tank battery location from the adjacent road, facing Southeast. See comments under Photo 7.



**Photo 10.** Photo taken of the reference area to the tank battery location, southeast of the location, facing South. Photo illustrates shrub and grass vegetation.





Inspection Photos  
Location Name: HSR-FOSTER #4-35  
Location ID: 330386



**Photo 11.** Photo taken of reference area to the well location, northeast of the location, facing East. Photo illustrates rye cropland.

