

Final Reclamation Inspection

June 12, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 305078

Inspection Document #: 718800446

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MOSER H #26-14
Location ID: 305078



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows from seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation, including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, were observed across the location.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: MOSER H #26-14
Location ID: 305078



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: MOSER H #26-14
Location ID: 305078



Photo 5. Photo taken of the access road to the well location, facing Northeast. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding. However, bare ground and weedy annual vegetation, including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), was observed across the location.



Photo 6. Photo taken of the access road, from the well location, facing Southwest. See comments under Photo 5.



Inspection Photos
Location Name: MOSER H #26-14
Location ID: 305078



Photo 7. Photo taken of reference area to the well location, north of the location, facing Northeast. Photo illustrates perennial grass and sand sagebrush, with some annual vegetation.