

Final Reclamation Inspection

June 12, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 327379

Inspection Document #: 718800452

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRR 53 PAN AM UT /P/ #2
Location ID: 327379



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill rows from seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: UPRR 53 PAN AM UT /P/ #2
Location ID: 327379



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: UPRR 53 PAN AM UT /P/ #2
Location ID: 327379



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground and weedy annual vegetation present at the location.



Photo 6. Photo taken of the access road, from the well location, facing Southwest. Photo illustrates that final reclamation has taken place, but the location is dominated by weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed Species.



Inspection Photos
Location Name: UPRR 53 PAN AM UT /P/ #2
Location ID: 327379



Photo 7. Photo taken of reference area to the well location, north of the location, facing West. Photo illustrates sand sagebrush (*Artemisia filifolia*), with some weedy annual vegetation, including cheatgrass (*Bromus tectorum*).