

# Final Reclamation Inspection

June 12, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 330443

Inspection Document #: 718800459

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-FOSTER #5-35  
Location ID: 330443



**Photo 1.** Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. The site is dominated by weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 2.** Photo taken from the well location, facing East. See comments under Photo 1.





Inspection Photos  
Location Name: HSR-FOSTER #5-35  
Location ID: 330443



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 1.



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 1.





Inspection Photos  
Location Name: HSR-FOSTER #5-35  
Location ID: 330443



**Photo 5.** Photo taken of ground cover at the location. Photo illustrates bare ground and weedy annual vegetation, including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



**Photo 6.** Photo taken of the access road, from the well location, facing west. Photo illustrates that final reclamation has taken place, but bare ground remains and the the location is dominated by weedy annual vegetation.





Inspection Photos  
Location Name: HSR-FOSTER #5-35  
Location ID: 330443



**Photo 7.** Photo taken of reference area to the well location, west of the location, facing west. Photo illustrates perennial grass with some weedy annual vegetation.

