

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10A (K4CBW) Pad

Location #: 334756



Photo # 9294 From entrance to location



Photo # 9295 Location



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10A (K4CBW) Pad

Location #: 334756



Jul 2, 2025 at 11:42:12 AM
CO

Photo # 9296 Location



Jul 2, 2025 at 11:45:57 AM
CO

Photo # 9297 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10A (K4CBW) Pad

Location #: 334756



Jul 2, 2025 at 11:46:27 AM
CO

Photo # 9298 Location



Jul 2, 2025 at 11:46:51 AM
CO

Photo # 9299 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10A (K4CBW) Pad

Location #: 334756



Photo # 9300 Unmarked deadman



Photo # 9301 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10A (K4CBW) Pad

Location #: 334756



Photo # 9302 Same unmarked deadman



Photo # 9303 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GMR 4-10A (K4CBW) Pad

Location #: 334756



Photo # 9304 Methanol tank label contains inaccurate information