

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 138-21 Pad

Location ID: 324136



Photo # 9465 From entrance to location




Photo # 9466 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 138-21 Pad

Location ID: 324136



Photo # 9467 Location




Photo # 9468 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 138-21 Pad

Location ID: 324136



Photo # 9469 Location




Photo # 9470 Unused flowline does not comply with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 138-21 Pad

Location ID: 324136



Photo # 9471 Unused flowline does not comply with CECMC rules