

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 56-21 Pad

Location ID: 335062



Jul 2, 2025 at 2:01:29 PM  
CO



Jul 2, 2025 at 2:02:23 PM  
CO

Photo # 9511 From entrance to location

Photo # 9512 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 56-21 Pad

Location ID: 335062



Photo # 9513 Location



Photo # 9514 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 56-21 Pad

Location ID: 335062



Photo # 9515 Location



Photo # 9516 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 56-21 Pad

Location ID: 335062



**Photo # 9517 Open ended piping on separator/wildlife hazard/available for entry by wildlife**



**Photo # 9518 Open ended piping on separator/wildlife hazard/available for entry by wildlife**