

Operator: EXTRACTION OIL & GAS INC

Location Name: Enright 18-N

Loc ID: 454492

Inspection: 697011638



Exhibit A



Exhibit B



Exhibit C

CA: Electric cables and spools on location, see attached photos. Comply with Rule 606.

CA Resolution: Operator has addressed the issue in order to comply with Rule 606.

CA: Separator #10 burner stack has been removed, leaving fire tube unscreened, see attached photos. Install wildlife screen per Rule 608.b.(7).

CA Resolution: Operator has installed screens in order to comply with Rule 608.b.(7).