

Inspection Photos

Loc: 488235

Operator: BNL (ENTERPRISE) INC

Inspection Date: 7/2/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 7/2/2025

Inspection Photos



Photo 2. Facing toward the topsoil pile.



Inspection Photos



Photo 3. Facing northeast toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:488235 | Date: 7/2/2025

Inspection Photos



Photo 4. There is erosion beginning to occur along the fill slope of the location.



Inspection Photos



Photo 5. Facing southwest corner of the location. The sediment trap has filled in with sediment and needs maintenance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:488235 | Date: 7/2/2025