

Inspection Photos

Loc #: 484357

Operator: DESERT EAGLE OPERATING

Inspection Date: 7/2/2025

County: Las Animas



Inspection Photos



Photo 1. Facing south toward the wellsite.



Inspection Photos



Photo 2. Facing toward the west side of location. It appears there is desirable vegetation beginning to establish.



Inspection Photos



Photo 3. Facing west toward the flowline area. The wood pallet and straw bale need to be removed.



Inspection Photos



Photo 4. Facing east toward the flowline area. The straw bales were not used and need to be removed. The straw bales used were not certified weed free.

