

WELL NAME: SPHINX 22-36, API #: 071-08941, INSP. # 716301204



PHOTO 1: WELL SIGN







**PHOTO 2: LOCATION.**





**PHOTO 3: WELLHEAD AND EQUIPMENT.**







**PHOTO 4: WEEDS NOT MAINTAINED ALONG ROW AND ON LOCATION (SEE PHOTO ON FOR WEEDS ON LOCATION). **MAINTAIN WEEDS PER RULE 606. CA DATE 7-14-2025.****





## Calibration Report

Report Date **5/15/24 9:20 AM**

Collection Time **5/15/24 9:22 AM**

### Section 1 - Meter

Device ID **100108941**

Location **Sphinx 22-36**

System

Contact # **719-846-7898**

Field

**Raton Basin**

State

**Colorado**

Producer

**Evergreen Natural Resources**

Purchaser

**Colorado Interstate Gas**

### Section 2 - Setup

Current Plate Size

**0.375**

Pipe Size

**1.941**

Atmos. Pressure

**11.15**

Pressure Base

**14.73**

Tap Type

**Flange**

Specific Gravity

**0.564**

SP Tap Location

**Up Stream**

Temperature Bias

**0**

Temperature Base

**60**

Plate Inspected?

Yes ☒ No ☐

Dirty

Yes ☐ No ☒

Nicked?

Yes ☐ No ☒

Edges Sharp?

Yes ☒ No ☐

Plate Mic'd

Yes ☐ No ☒

Warped?

Yes ☐ No ☒

Seal Ring Damaged?

Yes ☐ No ☒

Pitted

Yes ☐ No ☒

Bevel Downstream

Yes ☒ No ☐

### Section 3 - Meter Tube Inspection

Tube Inspected?

Yes ☐ No ☒

Dirty?

Yes ☐ No ☒

Pitted?

Yes ☐ No ☒

Nicked?

Yes ☐ No ☒

### Section 4 - Calibration Data

**PHOTO 4: ANNUAL METER CALIBRATION IS PAST DUE. Calibrate gas metering equipment annually to comply with rule 430.d.(1). CA DATE 8-2-2025.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources