

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

05/23/2025

Document Number:

404215931

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10690 Contact Person: Brent Bongers
Company Name: IMPETRO RESOURCES LLC Phone: (361) 9355633
Address: 558 CASTLE PINES PKWY UNIT B-4 Fax: ()
City: CASTLE PINES State: CO Zip: 80108 Email: bbongers@impetroresources.com

Identification Information

API Number: 05 - - ECMC Facility ID: 102684 Initial Form 19 or 27 Document number:
Facility Name: TUTTLE WALKER Facility Number: Facility Type: PIT
Location QtrQtr: NENW Section: 32 Township: 2N Range: 54W Meridian: 6
County: WASHINGTON Field Name: URANUS
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS INC. Agent Name: Evan Sky Title: Staff Scientist
Phone Number: 9708292232 Email: esky@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 03/19/2025

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 233588 Facility Name: PIERCE 1 Facility Type: Oil and Gas Well
Location: QtrQtr: SWSW Sec: 9 Twp: 3S Range: 56W Meridian: 6
County Name: WASHINGTON Latitude: 39.800460 Longitude: -103.665790

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 126809 Document Name: EDD File Name: 2025_0318_Pierce 909J- EDD.xlsx
Sample Type: Matrix:
Facility ID: 233588 Sample ID: 667390 Sample Name: Walker Ruth (Tuttle Walker) Sample Date: 03/18/2025
Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j subsequent sample
Project Number: 29366 Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Elevation Diagnostics Lab Sample ID: AA19193

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
233588	404215994	2025_0319_Walker Ruth (Tuttle Walker) 909J Lab Report.pdf	Analytical Laboratory Report	PDF

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
667390	121-06866	WALKER*RUTH 1	Rule 909.j subsequent sample

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	Deleted. The sample(s) included in this form were submitted to the ECMC in form 404215732.	06/25/2025
Total: 1 comment(s)		