

Inspection Photos

Loc #: 484359

Operator: DESERT EAGLE OPERATING

Inspection Date: 7/2/2025

County: Las Animas



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the access road. The sign has fallen over shown at red arrow.



Inspection Photos



Photo 2. Facing southeast toward the location. There are a pile of wattles partly in the road. There are degraded wattles shown at red arrow.



Inspection Photos



Photo 3. Facing southeast toward the disturbed location. This area is not revegetating and is not stabilized.



Inspection Photos



Photo 4. There is a compressor being set up at the location.



Inspection Photos



Photo 5. There is some fluids that are staining the soil. Oily fluids need to be cleaned up and properly disposed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 484359 | Date: 7/2/2025

Inspection Photos



Photo 6. There are chemical barrels stored on location. Secondary containment will need to be implemented.

