

Inspection Photos

Loc: 386457

Operator: AMOCO PRODUCTION COMPANY

Inspection Date: 7/7/2025

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. There is erosion along the road. Red arrow points to a hard hat in the erosion channel for scale.



Inspection Photos



Photo 2. Facing northeast along the road. It appears stormwater is running down the road causing erosion and needs an additional diversion BMP off the road (e.g water bar, culvert, ect.).



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:386457 | Date: 7/7/2025

Inspection Photos



Photo 3. Further along the road facing south.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:386457 | Date: 7/7/2025

Inspection Photos



Photo 4. Facing southeast at the location.



Inspection Photos



Photo 5. Drone aerial photo facing southeast at the well pad location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:386457 | Date: 7/7/2025

Inspection Photos



Photo 6. Drone aerial photo facing east at the location.



Inspection Photos



Photo 7. Facing toward the fill slope of the location at the north side of the location..



Inspection Photos



Photo 8. Facing toward the middle of the fill slope.



Inspection Photos



Photo 9. Facing north along the bottom of the fill slope. It appears the silt fence needs maintenance at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:386457 | Date: 7/7/2025

Inspection Photos



Photo 10. South side of the location facing northeast.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:386457 | Date: 7/7/2025

Inspection Photos



Photo 11. Drone aerial overview facing southeast showing beginning of access road and location shown at red arrows.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:386457 | Date: 7/7/2025