

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 9853 From entrance to location




Photo # 9854 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 9855 Location



Photo # 9856 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 9857 Location



Photo # 9858 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 2118 From inspection/audit 708906569 conducted on 05/21/2025 Hole near wellhead/wildlife & personnel hazard



Photo # 9859 Hole near wellhead/wildlife & personnel hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC ROE 24-4 (D24W) Pad

Location #: 323904



Photo # 2119 From inspection/audit 708906569 conducted on 05/21/2025 Hole near wellhead/wildlife & personnel hazard



Photo # 9860 Hole near wellhead/wildlife & personnel hazard

