

Final Reclamation Inspection

June 20, 2025

Operator: NOBLE ENERGY INC - 100322

Location ID: 328317

Inspection Document #: 718800483

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CANNON #H 35-3D
Location ID: 328317



Photo 1. Photo taken from the well location, facing North. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding. However, vegetation has not established to Rule 1004 standards.



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: CANNON #H 35-3D
Location ID: 328317



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: CANNON #H 35-3D
Location ID: 328317



Photo 5. Photo taken of the access road to the well location, facing Southeast. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 6. Photo taken of the access road, facing Northwest. See comments under Photo 5.

Inspection Photos
Location Name: CANNON #H 35-3D
Location ID: 328317



Photo 7. Photo taken of the reference area, located east of the well location, facing northeast. Photo illustrates sand sagebrush (*Artemisia filifolia*) and annual vegetation including prairie sunflower (*Helianthus petiolaris*).

