

Inspection Photos

July 7th, 2025

Operator: American Helium LLC

Location ID: 322122

Inspection Document #: 714002276

Dolores County, CO

Township: SWSW 20 39N 19W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Papoose Canyon 2-20

Location ID: 322112



Photo 1. View of access road facing towards location, access road meets 1004 vegetation requirements.



Inspection Photos

Location Name: Papoose Canyon 2-20

Location ID: 322112

July 7, 2025
38° NE



Photo 2. View of the project area taken from the southern edge facing center.

Inspection Photos

Location Name: Papoose Canyon 2-20

Location ID: 322112



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos

Location Name: Papoose Canyon 2-20

Location ID: 322112



Photo 4. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: Project area appears consistent with adjacent reference area.

Inspection Photos

Location Name: Papoose Canyon 2-20

Location ID: 322112

July 7, 2025
229° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Rabbit Brush and Crested Wheatgrass.

API #: 033-06100